



Movement that inspires

## Campanie rechemare service

**Model:** STNGER CK

**Intervenție:** resoftware ECU sau  
înlocuire pompă presiune benzină

	V.I.N	DIST CODE	NATION
1	KNAE351ABJ6007199	C28VA	ROMANIA
2	KNAE351ABJ6007198	C28VA	ROMANIA
3	KNAE351ABJ6030714	C28VA	ROMANIA
4	KNAE351ABJ6030718	C28VA	ROMANIA
5	KNAE351ABJ6037895	C28VA	ROMANIA
6	KNAE351ABJ6037900	C28VA	ROMANIA
7	KNAE351ABJ6041389	C28VA	ROMANIA
8	KNAE351ABJ6041390	C28VA	ROMANIA
9	KNAE351ABJ6041582	C28VA	ROMANIA
10	KNAE351ABK6046854	C28VA	ROMANIA
11	KNAE351ABK6046855	C28VA	ROMANIA
12	KNAE351ABK6046847	C28VA	ROMANIA
13	KNAE351ABK6046850	C28VA	ROMANIA
14	KNAE351ABK6046846	C28VA	ROMANIA
15	KNAE351ABK6055226	C28VA	ROMANIA
16	KNAE351ABK6055253	C28VA	ROMANIA
17	KNAE351ABK6055222	C28VA	ROMANIA
18	KNAE351ABK6065949	C28VA	ROMANIA
19	KNAE351ABK6066603	C28VA	ROMANIA
20	KNAE351ABL6071912	C28VA	ROMANIA
21	KNAE351ABL6074604	C28VA	ROMANIA
22	KNAE351ABL6078699	C28VA	ROMANIA
23	KNAE351ABL6078698	C28VA	ROMANIA
24	KNAE351ABL6081082	C28VA	ROMANIA
25	KNAE351ABL6081083	C28VA	ROMANIA
26	KNAE351ABL6085120	C28VA	ROMANIA
27	KNAE351ABL6090564	C28VA	ROMANIA