



Movement that inspires

Campanie rechemare service

Model: Picanto TA

Intervenție: Înlocuire furtune de pe gât
alimentare rezervor

VIN	Număr campanie
KNABE511ACT071845	181033
KNABE511ACT072159	181033
KNABE511ACT072259	181033
KNABE511ACT081652	181033
KNABE511ACT081749	181033
KNABE511ACT082101	181033
KNABE511ACT082140	181033
KNABE511ACT160333	181033
KNABE511ACT160404	181033
KNABE511ACT160406	181033
KNABE511ACT160724	181033
KNABE511ACT160750	181033
KNABE511ACT160839	181033
KNABE511ACT161045	181033
KNABX312ACT160437	181033
KNABX312ACT160676	181033
KNABX511ACT081611	181033
KNABX511ACT081653	181033
KNABX511ACT081750	181033
KNABX511ACT082017	181033
KNABX511ACT082018	181033
KNABX511ACT082032	181033
KNABX511ACT160327	181033
KNABX511ACT160434	181033
KNABX512ACT105389	181033
KNABX512ACT160752	181033
KNABX512BCT106613	181033